

**IMPORTANT INFORMATION ABOUT YOUR DRINKING WATER
MONITORING REQUIREMENTS NOT MET FOR**

MOUNT ZION P S D, WV3300702

We are required to monitor your drinking water on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. Between 10/1/2025 and 10/31/2025, we failed to submit the required samples as indicated below and therefore cannot be sure of the quality of our drinking water during that time.

What should I do?

There is nothing you need to do at this time.

The table below lists the required monitoring and the compliance period.

Required Monitoring	Compliance Period
36, MONITORING, RTN/RPT MAJOR (SWTR-FILTER) CHLORINE Missing Required Chlorine Residual Associated With Entry Point to Distribution System	10/1/2025 to 10/31/2025

What happened? What is being done? (Describe corrective action)

System Failed To Record Chlorine Residual On Entry
Point to Distribution System. System has Established
New Protocols on Recording future Chlorine Residuals

For more information, please contact Trenten Cunningham at 304-354-7799
(Contact name) (Phone number)
Or 4418 S. Calhoun Hwy, Grantsville WV 26147
(Mailing address)

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

This notice is being sent to you by: **MOUNT ZION P S D**

State Water System ID #: WV3300702

Date Distributed: 3-10-23